

No legal surveys exist for this corner. Corner referenced by Miller on 12/15/76 and called a road nail. Corner referenced by Wilcoxen on 3/11/77 and called a R.R. spike. This corner was re-established working from property corner markers found in the SE quarter of 10-16-03. These markers identify properties shown on the Union Title Co. arb maps for the section. The positions of the markers are in agreement with each other. An attempt was made to work from the record plat of Reliable Co. The Highlands plat book 18 page200, on the West Side of Grandview Drive, but no stones or other markers as called out on the plat could be found or re-established with certainty. Corner referenced by Wilcoxen on 6/11/86 and called a R.R. spike. Corner referenced by Kiste on 10/10/95 and called a R.R. spike. Corner referenced by Wilcoxen on 7/18/2000 and called a R.R. spike. Corner excavated by Kiste on 5/20/2003 and a R.R. spike was found 2" down. No stone or other monuments were found. A #205 cast iron Harrison monument was set in position as the corner.

REF.	DISTANCE	DESCRIPTION
1.	43.85	Cut 'x' SW lift station mahole
2.	53.69'	Top nut of fire hydrant
3.	53.00	Center: 4"x4" concrete property corner monument
4.	48.24'	Cut 'x' E-rim sewer manhole
5.	30.00	Cut 'x' NE-bolt of light pole #212-332 B
6,	30.49	Center of 2" pipe 12" high